


STATE OF UTAH  
DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING  
1594 West North Temple - Suite 1210  
Box 145801  
Salt Lake City, Utah 84114-5801  
Telephone: (801) 538-5291  
Fax: (801) 359-3940



ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. General Information

1. Report Time Period: From (mo./yr.) 1/98 To (mo./yr.) 1/99
2. DOGM File Number (Mine No): 51230057
3. Mine Name: ML 47821 - ML 46956 - Cactus
4. Mineral(s) Mined (or permitted to mine): Gemstones & mineral specimens
5. Type of mine ☒ Surface Mine or ☐ Underground Mine
6. Legal Description (Location of Lands Affected):  
NE 1/4, SE 1/4, SW 1/4, Section 28, Township 12S, Range 11W  
NW 1/4, NW 1/4, NW 1/4, Section 16, Township 13S, Range 11W  
SE 1/4, SW 1/4, NW 1/4, Section 16, Township 12S, Range 11W
7. Name of Operator or Company: Mike Sprunger
8. Permanent Street Address: Mike & Sandra Sprunger  
P.O. Box 38054  
Leamington, UT 84638  
City, State, Zip: \_\_\_\_\_  
Phone: (435) 857-2572
9. Company Representative (or designated operator):  
Name: Same  
Title: Owner  
Business Address: Same  
City, State, Zip: ?  
Phone: ?  
☐ Please check if any of the above information has changed since previous year.

II. Mining and Reclamation

1. Was there any mine related activity during the past year? Yes ☒ No ☐
2. If no - what was the last year of activity? \_\_\_\_\_
3. If yes - how much ore or mineral was mined? ~45 yards rock moved.

4. Briefly describe the type of work performed, volume of material moved, and any new or additional surface disturbances that occurred during the past year.  
Cactus: About 4 yd moved blasting in existing pit  
ML 46954: About 5 yd blasted within area of old workings.  
ML 47821: About 35 yd backhoe & blasting work  
deepening, then refilling existing hole
5. How much **additional acreage** was disturbed during the past year? None
6. How much acreage was **reclaimed** during the past year? None
7. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.  
None
8. What is the **total disturbed acreage of entire project** at years end? 10.2 acre
9. Briefly summarize any mining and/or reclamation plans for the upcoming year.  
Like 1998; Mostly work down under existing  
diggings, then refill

**NOTE:** Section III., "Additional Information" applies only to **large mining operations**.

### III. Additional Information

1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.
2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.

### IV. Signature Requirement

I hereby certify that the foregoing is true and correct.

Name (Typed or Print):

Mike Sprunger

Title of Operator:

Owner

Signature of Operator:

Mike Sprunger

Date:

1/19/99

jb  
a:\forms\MR-AR

